

AD-A082 819

ILC DOVER FREDERICA DE PROTECTIVE EQUIPMENT DIV  
GLOVE TOOLING REDESIGN.(U)  
MAR 80 C R SANDY

F/G 13/8

DAAK11-79-C-0066  
NL

UNCLASSIFIED

100  
MAR 1980



END  
DATE  
FILED  
5-80  
DTIG

ADA082819

LEVEL

GLOVE TOOLING REDESIGN

(15) DAAK11-79-C-0066

2

10  
Charles R. Sandy  
Project Engineer  
Protective Equipment Division  
ILC DOVER  
P.O. Box 266  
Frederica, Delaware  
19946

DTIC  
ELECTED  
APR 9 1980  
S D

11  
28 March 1980

12  
13

9  
Final Report, for Period 12 June 1979 - 29 March 1980

Prepared For:

CDR, ARRADCOM  
CML/Ballistics Procurement  
APG (Edgewood Area), Maryland  
21010

DCASR Philadelphia  
P.O. Box 7730  
Philadelphia, Pennsylvania  
19101

This document has been approved  
for public release and sale; its  
distribution is unlimited.

The view, opinions, and/or findings contained in this report are  
those of the author and should not be construed as an official  
Department of the Army position, policy or decision, unless so  
designated by other documentation.

444692

80 4 032

B

DDC FILE COPY

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER  DAAK11-79-C-0066-04	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle)  Glove Tooling Redesign		5. TYPE OF REPORT & PERIOD COVERED  Final Report 12 June 79 -- 29 March 80
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)  Charles R. Sandy, Project Engineer Protective Equipment, ILC DOVER		8. CONTRACT OR GRANT NUMBER(s)  DAAK11-79-C-0066
9. PERFORMING ORGANIZATION NAME AND ADDRESS  ILC DOVER P.O. Box 266 Frederica, Delaware 19946		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS  Task Order Number 4
11. CONTROLLING OFFICE NAME AND ADDRESS  CDR, ARRADCOM CML/Ballistics Procurement APG (Edgewood Area) Maryland 21010		12. REPORT DATE  28 March 1980
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)  DCASR Philadelphia P.O. Box 7730 Philadelphia, Pennsylvania 19101		13. NUMBER OF PAGES  Page 1 of 4
		15. SECURITY CLASS. (of this report)  Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release: Distribution Unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Outergarment DPE, Demilitarization Protective Ensemble		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  This task was authorized to redesign the glove attachment tooling on the DPE Outergarment so that the heat seal overlaps the cuff making peel loading impossible during inspection. The tooling was designed, fabricated, and tested. It succeeds in preventing peel loading of the seam while maintaining the same shear strength as with the previous tooling.		

FOREWARD

The work reported herein was conducted by ILC DOVER, Frederica, Delaware, for ARRADCOM, CML/Ballistics Procurement, APG (Edgewood Area), Maryland in accordance with Contract DAAK11-79-C-0066, Task Order Number 4. Mr. Donald R. Cohee was the Program Manager for ILC DOVER. Mr. Wayne Davis was the Contract Monitor for the Chemical Systems Laboratory. This work was accomplished between 12 June 1979 and 29 March 1980.

This technical report has been reviewed and is approved.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or special
A	

Mr. David M. English, Chief  
Combat Vehicle Section  
Physical Protection Division  
Chemical Systems Laboratory

## INTRODUCTION

This task was authorized to redesign the glove attachment heat seal tooling in order to eliminate the possibility of pulling the seam in the peel mode. In use, the seam is loaded in shear. Inspection procedures, however, can load the seam in peel, which can initiate glove failures at sites of seam misalignment. The object of the redesign in tooling was to make the glove attachment heat seal overlap the sleeve cuff, making peel loading impossible when the seam is inspected.

## COMPLETED ACTIVITY

The following work was performed during the completion of this task order:

- (1) The glove tooling was redesigned. The glove attachment seam can be made to overlap the cuff by changing the location of the scribed line. The first line indicates how far the separator is inserted in the glove, and the second line locates the sleeve cuff over the separator. This line is visible through the translucent glove material. The actual heat seal dies remain unchanged.
- (2) The new glove separators were fabricated, and the necessary drawings made. Seam samples were made, tested, and found adequate per specification. ECP Number 80-0058-004 includes these tool drawings and test results.
- (3) All changes to the specification, tool drawings and test results have been submitted with ECP Number 80-0058-004, proposing to implement these changes.

CONCLUSION

The redesigned glove tooling is available for use in the production of  
DPE Outergarments.